





Motorcraft

Rotunda

Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

009837 FIR No. Level: 1

US-US-3 **Version Number:** Release Date: 2004-11-24

1. Product and Company Identification

Product Name: Automotive Interior Spray Lacquer

Product Code: See Attachment

Application: Automotive interior touch-up paint

Supplier: Ford Motor Company

Attention: MSDS Information, P.O. Box 1899

Dearborn, Michigan 48121

1-800-392-3673

Emergency Telephone: Poison Control Center: 1-800-959-3673

> CHEMTREC: U.S. and Canada: 1-800-424-9300 CHEMTREC: International: 1-703-527-3887

2. Composition/Information on Ingredients

This chemical product is a preparation.

Chemical Name	CAS Number	Percent Concentration	Hazard Classification
ACETONE	67-64-1	30-40	HAZCOM MOC-ALL WHMIS 1 RQ
PROPANE	74-98-6	5-15	HAZCOM
N-BUTANE	106-97-8	5-15	HAZCOM WHMIS 1 RSMSREST
ETHYL ALCOHOL	64-17-5	5-10	HAZCOM RSMSREST WHMIS 0.1
METHYL ETHYL KETONE	78-93-3	5-10	CAA-HAP HAZCOM MOC-ALL RQ RSMSREST SARA 313 WHMIS 1
TOLUENE	108-88-3	5-10	CAA-HAP WHMIS 1 HAZCOM RQ RSMSREST SARA 313 MOC-ALL

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Page: Official Record Application: MATS 1 /







Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

009837 FIR No. Level: 1

Version Number: US-US-3 **Release Date:** 2004-11-24 85-68-7 **BUTYL BENZYL PHTHALATE** 1-5 RQ **RSMSREST** WHMIS 1 141-78-6 **ETHYL ACETATE** 1-5 **HAZCOM** RQ

WHMIS 1 13463-67-7 TITANIUM DIOXIDE **HAZCOM** 1-5

3. Hazards Identification

EXTREMELY FLAMMABLE

Health: Aspiration hazard if swallowed; can enter lungs and cause damage.

> This product is irritating to the eyes, respiratory system and skin. Overexposure may cause central nervous system depression. Extreme overexposure may result in unconsciousness and possibly

death.

Physical and Chemical Hazards: Contents under pressure.

Environment: Material contains a chemical which is a Hazardous Air Pollutant (HAP),

regulated by the United States Clean Air Act.

4. First-Aid Measures

Inhalation: If gas/fume/vapor/dust/mist from the material is inhaled, remove the

affected person immediately to fresh air. If irritation persists, get medical attention.

Skin Contact: Wash skin with soap and water.

If irritation persists, get medical attention.

Eye Contact: In case of contact with eyes, rinse immediately with plenty of water for

at least 15 minutes and seek medical attention.

Ingestion: If the material is swallowed, get immediate medical attention or advice

-- Do not induce vomiting.

Most Important Symptoms Effects: Headache, dizziness, nausea, and loss of coordination are indications

of excessive exposure to vapors or spray mists.

Redness and itching or burning sensation may indicate eye or

excessive skin exposure.

Notes to a Physician: This material, if aspirated into the lungs, may cause chemical

pneumonitis; treat the affected person appropriately.

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Official Record Application: MATS Page: 2 /



Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

FIR No. 009837 **Level**: 1

Version Number: US-US-3 Release Date: 2004-11-24

5. Fire-Fighting Measures

Extinguishing Media: Dry chemical, foam, carbon dioxide.

Specific Methods: Water may be an ineffective extinguishing medium.

Water may be used to cool exposed containers to prevent pressure

Rotunda

build-up and explosion when exposed to extreme heat.

Specific Hazards: Fire and Explosion hazards are DANGEROUS when this material is

exposed to heat or flame.

Due to pressure buildup, closed containers exposed to excess heat

may explode.

Vapors may form explosive mixture with air.

Protection of Firefighters: Fire fighters should be equipped with NIOSH-approved, self-contained

breathing apparatus (SCBA) and full protective clothing.

6. Accidental Release Measures

Personal Precautions: Avoid inhalation of vapors and contact with skin and eyes.

Eliminate all sources of ignition or flammables that may come into

contact with a spill of this material. Ventilate the contaminated area.

Environmental Precautions:No available information.

Methods for Cleaning Up: Absorb the spilled material with an inert absorbent (nonflammable)

material.

7. Handling and Storage

Handling:

Technical Measures: Keep this product from heat, sparks, or open flame.

Precautions and Advice for

Safe Handling:

Do not breathe gas/fumes/vapor/spray. Do not puncture or incinerate container.

Keep area ventilated. Do not smoke. Extinguish all flames, pilot lights, and heaters. Turn off stoves, electric tools and appliances, and any

other sources of ignition.

Storage:

Technical Measures: Eliminate all sources of ignition.

Storage Conditions: Ground all containers of this material.

Keep the container tightly closed and in a cool, well-ventilated place.

Owner: Ford Motor Company PRINTED DOCUMENT IS TRANSIENT Ford Proprietary

Application: MATS Page: 3 / 9 Official Record









Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

009837 FIR No. Level: 1

Version Number: US-US-3 **Release Date:** 2004-11-24

8. Exposure Controls/Personal Protection

Engineering Measures: Use local exhaust.

Exposure Limits:

Chemical Name TWA 8 hr STEL/C References ETHYL ALCOHOL 1000(ppm) **ACGIH** 1000(ppm) 1900(ppm) **OSHA ACETONE** 500(ppm) 750(ppm) **ACGIH** 1000(ppm) 2400(ppm) **OSHA** 1000(ppm) **PROPANE ACGIH** 1000(ppm) 1800(ppm) **OSHA** 200(ppm) METHYL ETHYL **ACGIH KETONE** 200(ppm) 590(ppm) OSHA **N-BUTANE**

1000(ppm) **ACGIH** OSHA

> 50(ppm) **ACGIH**

200(ppm) C **OSHA**

300(mg/m3)

ETHYL ACETATE 400(ppm) **ACGIH**

> 400(ppm) 1400(ppm) **OSHA**

TITANIUM DIOXIDE 10(mg/m3) **ACGIH**

> 15(ppm) **OSHA**

Personal Protective Equipment:

TOLUENE

Respiratory Protection: If engineering controls do not maintain airborne concentrations to a level

which is adequate to protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Hand Protection: None required for normal application of aerosol products where minimal

skin contact is expected. For long or repeated contact, wear chemical

resistant gloves such as nitrile gloves.

Eye Protection: Wear safety glasses with side shields.

Skin and Body Protection: Remove contaminated clothing and wash before reuse.

Hygiene Measures: When using this material, do not eat, drink or smoke.

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Official Record Application: MATS Page:









Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

FIR No. 009837 Level: 1

US-US-3 **Version Number:** Release Date: 2004-11-24

9. Physical and Chemical Properties

Specific Gravity: 0.78

Physical State: AEROSOL

AEROSOL Form:

N.AV Odor:

VARIOUS Color:

:Ha N.AV

Temperature Range During which Changes in Physical State Occur:

> -17.778|+172.222 °C (0|342 F) **Boiling Point:**

-4 °C TCC Flash Point:

Explosion Properties:

19 % UEL:

1 % LEL:

Vapor Density: >1 (AIR=1)

NA Solubility:

Viscosity: N.AV

>1 Ether = 1 **Evaporation Rate:**

10. Stability and Reactivity

Stability: This is a stable material.

Hazardous polymerization will not occur.

Hazardous Decomposition Products: Carbon monoxide, carbon dioxide, and other low molecular weight

hydrocarbons.

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Official Record Page: 5 / 9 Application: MATS



Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

FIR No. 009837 **Level**: 1

Version Number: US-US-3 Release Date: 2004-11-24

11. Toxicological Information

Inhalation: Intentional misuse by deliberately concentrating and inhaling the

contents may be harmful or fatal.

Skin Contact: Prolonged and/or repeated skin contact with this product may cause

irritation/dermatitis.

Chronic (Long Term) Toxicity: Based on animal studies, exposure to methyl ethyl ketone (MEK)

increases the onset of peripheral neuropathy caused by exposure to methyl butyl ketone (MBK), and/or n-hexane, and/or ethyl butyl ketone. MEK alone has not been shown to cause peripheral neuropathy. In a two year study, IARC indicates that lung tumors were observed in rats that had inhaled TITANIUM DIOXIDE dust at 250 mg/m3. This level is 25 times the current occupational exposure level (10 mg/m3) and is

not expected to be attainable in the workplace.

Prolonged and repeated exposure of pregnant animals to toluene (concentrations greater than 1500 ppm) has been reported to cause adverse fetal developmental effects. It has also been reported that variable growth deficiencies have occurred in human infants born to mothers who intentionally inhaled toluene containing products (e.g.,

glue).

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

12. Ecological Information

No specific aquatic data available for this product.

13. Disposal Considerations

Waste from Residues: Dispose of waste material according to Local, State, Federal, and

Provincial Environmental Regulation.

Contaminated Packaging: Do not crush, puncture or incinerate spent containers. Large numbers or

aerosol containers may require handling as a hazardous waste. Consult local, provincial, and federal agencies for the proper disposal method in

your area.

Owner: Ford Motor Company PRINTED DOCUMENT IS TRANSIENT Ford Proprietary

Application: MATS Page: 6 / 9 Official Record







Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

009837 FIR No. Level: 1

US-US-3 **Version Number:** Release Date: 2004-11-24

14. Transport Information

U.S. Department of Transportation (DOT) 49 - CFR 172.101

CONSUMER COMMODITY Proper Shipping Name:

Hazard Class / Division: ORM-D

Reportable Quantity (per

packaging):

CAS RQ Name 67-64-1 13123 **ACETONE** 78-93-3 81967 METHYL ETHYL KETONE 85-68-7 7519 **BUTYL BENZYL PHTHALATE** 108-88-3 12500 **TOLUENE** 141-78-6 >100000 ETHYL ACETATE

Canadian Transportation of Dangerous Goods (T.D.G.) -TDGR Schedule II

CONSUMER COMMODITY Proper Shipping Name:

UN Number:

Hazard Class / Division: **NONE**

Packing Group:

Secretary of Communication and Transportation (SCT)- NOM-002-SCT2/1994 (Mexico)

Proper Shipping Name: **AEROSOLES**

UN Number: UN1950

Hazard Class/Division: 2.1

Label: FLAMMABLE GAS

International and Domestic Air Transportation - ICAO & IATA Section 4.2

Proper Shipping Name: Aerosols, flammable

UN Number: UN1950

Hazard Class/Division: 2.1

Label: FLAMMABLE GAS

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Page: 9 Official Record Application: MATS 7 /







Motorcraft

Rotunda

Material Safety Data Sheet

Product Name: Automotive Interior Spray Lacquer

FIR No. 009837 **Level**: 1

Version Number: US-US-3 Release Date: 2004-11-24

International Water Transportation - IMDG Code Amendment 31-02

Proper Shipping Name: Aerosols
UN Number: UN1950

Hazard Class/Division: 2.1
Ems Number: 2-13

Label: FLAMMABLE GAS

15. Regulatory Information

The components of this product are listed on the TSCA Inventory

This product contains a toxic chemical or chemicals subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372.

California Proposition 65: WARNING: This product contains a chemical known to the State of California to cause birth defects or other reproductive harm.

California Proposition 65: WARNING: This product contains a chemical known to the State of California to cause cancer.

This product contains an ingredient(s) considered to be an environmental hazardous substance(s) by the State of New Jersey.

This product contains an ingredients(s) considered to be a hazardous substance(s) by the State of New Jersey. Material contains a chemical which is a Ford Motor Company Material of Concern. Use and release of this material should be minimized to the greatest extent possible.

16. Other Information

Key/Legend: N.AP = Not applicable; N.AV = not available; ND = Not determined or No data; TLV = Threshold limit value; TWA = Time-weighted average; STEL = Short-term exposure limit; C = Ceiling limit

Preparation Information: The chemical identification and properties for this material were provided

by the manufacturer. For Canadian locations, a manufacturer's MSDS is available upon request. Health and safety information has been evaluated by the Occupational and Environmental Health Sciences

Department, Ford Motor Company, Central Laboratory Building - Room

S-120, 15000 Century Drive, Dearborn, MI 48120

Disclaimer: The information on this data sheet represents our current data and is

accurate to the best of our knowledge as to the proper handling of this product under normal conditions and in accordance with the application specified on the packaging and/or technical guidance literature. Any other use of the product which involves using the product in combination with any other product or any other process is the responsibility of the

user.

Owner: Ford Motor Company PRINTED DOCUMENT IS TRANSIENT Ford Proprietary
Application: MATS Page: 8 / 9 Official Record

Ford Motor Company,





Rotunda

Material Safety Data Sheet

Product Name:

Automotive Interior Spray Lacquer

FIR No.

009837

Level: 1

Version Number:

US-US-3

Release Date: 2004-11-24

Attachment

Product Code

Container Size

Part of Kit

Kit Product Code

M4JZ-19M547-XXXXH 13 oz aerosol

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Page: 9 / 9 Official Record Application: MATS