

**MANDATORY INSTRUCTIONS FOR THE USE OF “COLD CLEANING
DEGREASING UNITS” or” PART WASHER UNITS”**

THIS DEGREASER UNIT LID MUST BE KEPT CLOSED AT ALL TIMES, EXCEPT WHEN ACTUALLY CLEANING PARTS, AND WHEN PARTS ARE BEING PLACED INTO OR BEING REMOVED FROM THE DEGREASER.

THE LEAD FUSIBLE LINK MUST HAVE INTEGRITY AND BE IN PLACE AT ALL TIMES FOR COMPLIANCE.

NOTHING CAN IMPEDE THE COMPLETE CLOSING OF THE LID AT ANY TIME WHILE THE UNIT IS ON SITE.

ALL MANDATORY SAFETY AND PRODUCT INFORMATION LABELING ON THE DEGREASER PART WASHER MUST BE ACCURATE AND LEGIBLE.

THE CHEMICAL M.S.D.S. INFORMATION MUST BE AVILABLE AT ALL TIMES AND BE CURRENT AND ACCURATE.

ALL PROPER PRECAUTIONS MUST BE TAKEN WHEN USING THIS PETROLEUM BASED, IGNITABLE, PETROLEUM NAPHTHA “MINERAL SPIRITS”

PERSONAL PROTECTIVE EQUIPMENT MUST BE WORN WHEN USING THIS DEGREASER PART WASHER. THIS INCLUDES MANDATORY EYE PROTECTION (GOGGLES OR SAFETY GLASSES) AND PROPERLY RATED CHEMICAL RESISTANT GLOVES.

ANY PROBLEMS THAT ARISE TO CAUSE THIS SET OF PROCEDURES TO BE COMPROMISED MUST BE IMMEDIATELY REPORTED TO THE APPROPRIATE MANAGEMENT PERSONELL. IMMEDIATELY AT THAT TIME THE COLD DEGREASER PART WASHER UNIT MUST BE UNPLUGGED, LID CLOSED AND LABELLED AND PLACED OUT OF COMMISION UNTIL THE NON COMPLIANCE ISSUE IS CORRECTED.

THANK YOU FOR YOUR COOPERATION!
THE MANAGEMENT